

May 23, 2023

Mr. Gregory Vismara Vice President Engineering Gillig, LLC 451 Discovery Drive Livermore, CA 94551

Subject: Electrical Short-Circuit in Fuse Box

Dear Mr. Vismara:

This letter serves to acknowledge Gillig, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: GILLIG/LOW FLOOR/2022

Mfr's Report Date: May 18, 2023

NHTSA Campaign Number: 23V-356

Components: ELECTRICAL SYSTEM

Potential Number of Units Affected: 50

Problem Description:

Gillig, LLC (Gillig) is recalling certain 2022 Low Floor CNG transit buses. An electrical failure may cause a short-circuit in the fuse box mounted underneath the driver's seat platform.

Consequence:

An electrical short-circuit can increase the risk of a fire.

Remedy:

Dealers will install new busbars, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Gillig customer service at 1-510-264-5073 or 1-800-735-1500.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107MR 23V-356

Please ensure the following requirements are met:

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

Gillig, LLC's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Alae Anoly

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

