

Part 573 Safety Recall Report

23V-408

Manufacturer Name : Imagine Fiberglass Products Inc.

Submission Date : JUN 06, 2023

NHTSA Recall No. : 23V-408

Manufacturer Recall No. : 2023-01



Manufacturer Information :

Population :

Manufacturer Name : Imagine Fiberglass Products Inc.

Number of potentially involved : 27

Address : 560 Weber St North

Estimated percentage with defect : 100 %

Waterloo 00 N2L 5C6

Company phone : 8048751

Vehicle Information :

Vehicle 1 : 2021-2023 L'Air Camper 1300/4500

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Campers with the Suburban SDS2 2-Burner Cooktop, Stock # 3032AST

Production Dates : JAN 04, 2021 - MAY 15, 2023

VIN Range 1 : Begin : 2F9BC13SONA105011 **End :** 2F9LT15S7NA105007 Not sequential

Description of Defect :

Description of the Defect : On L'Air Camper 1300 and 4500 RVs produced between 2021 through 2023 and equipped with a Suburban SDS2 cooktop, the aluminum tubes that connect the gas valves to the cooktop burners could crack. If this happens, the tubes could leak propane when the top burner gas valve is opened to use the appliance.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A propane gas leak could create the risk of a fire or explosion if ignited which, could result in personal injury.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : Suburban SDS

Component Description : 2 burner cooktop

Component Part Number : 3032AST

Supplier Identification :

Component Manufacturer

Name : Suburban Manufacturing Co

Address : 676 Broadway St
Dayton Texas 37321

Country : United States

Chronology :

We were notified by our supplier of the Suburban cooktop on May 1, 2023.

Description of Remedy :

Description of Remedy Program : We are working with Suburban and our distributor, GLP Canada, to provide customers with repair options most convenient for them. Local customers may choose to bring their L'Air Camper to our L'Air Camper manufacturing facility in Waterloo for us to conduct the repair. Customers for whom this is not a viable option may bring their L'Air Camper to any authorized RV repair centre in Canada or the US. Please note: it is imperative that the repair be executed by an authorized RV service technician. With proper documentation, Suburban will reimburse owners for the retail cost of an SDS2 cooktop if it was replaced prior to the issuing of this recall.

How Remedy Component Differs from Recalled Component : Suburban Manufacturing has provided a field recall kit with a bracket assembly to correct the issue.

Identify How/When Recall Condition was Corrected in Production : Campers which have been delivered will be fixed using the field kit as per above. Campers still in production will be furnished with an SDS 2 stock # 3033 AST.

Recall Schedule :

Description of Recall Schedule : Identify which campers require retrofit.

Identify which customers have taken delivery and prepare notification letters accordingly.

Planned Dealer Notification Date : JUN 06, 2023 - JUN 28, 2023

Planned Owner Notification Date : JUN 06, 2023 - JUN 28, 2023

* NR - Not Reported