

Part 573 Safety Recall Report

23V-435

Manufacturer Name : Airstream, Inc.**Submission Date :** JUN 21, 2023**NHTSA Recall No. :** 23V-435**Manufacturer Recall No. :** NR**Manufacturer Information :****Manufacturer Name :** Airstream, Inc.

Address : 419 West Pike Street
PO Box 629 Jackson Center OH
45334-0629

Company phone : 937-596-6111**Population :****Number of potentially involved :** 137**Estimated percentage with defect :** NR**Vehicle Information :****Vehicle 1 :** 2023-2023 Airstream Bambi**Vehicle Type :** TRAILERS**Body Style :** UNKNOWN**Power Train :** NR

Descriptive Information : To determine the population, Airstream is including all model year 2023 16' RB Bambi units which began production on 4/25/2022, and ended the affected population on 5/15/2023. This is the date the correction was made in production.

Production Dates : APR 25, 2022 - MAY 15, 2023**VIN Range 1 : Begin :** 1STHMAC13PJ563373 **End :** 1STHMAC13PJ568802 ☐ Not sequential**Description of Noncompliance :**

Description of the Noncompliance : Fresh Water Capacity was inaccurately entered as 192 gallons of water in the Model Parameter Maintenance module, and because of this understated the Caargo Carrying Capacity of the 16' RB Bambis

FMVSS 1 : 110 - Tire selection and rims**FMVSS 2 :** NR

Description of the Safety Risk : The non-compliance is the at we have overstated the fresh water capacity, and understated the cargo carrying capacity.

Description of the Cause : The non-compliance is the at we have overstated the fresh water capacity, and understated thee cargo carrying capacity.

Identification of Any Warning that can Occur : None

Involved Components :

Component Name 1 : Weight Label

Component Description : Cargo Capacity/Tire Information

Component Part Number : N/A

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

5/15/2023 - Identified a discrepancy with the weight label carrying capacity. 5/18/2023 - The Safety committee convened and initiated an investigation into the label issue. 6/16/2023 - The investigation was completed and it was decided to submit a 573 to NHTSA do to a FMVSS-110 non-compliance recall.

Description of Remedy :

Description of Remedy Program : Airstream will mail the corrected weight labels to the retail owners and Airstream dealer base along with instructions on how to place/install the labels. This will be done at no cost to the owner.

How Remedy Component Differs from Recalled Component : 2023 16' RB Bambi trailers manufactured after 5/15/2023 with have the correct weight label information.

Identify How/When Recall Condition was Corrected in Production : Production began manufacturing with the corrected weight label on 5/16/2023.

Recall Schedule :

Description of Recall Schedule : Airstream will send dealer and owner notification letters once approved by NHTSA.

Planned Dealer Notification Date : AUG 20, 2023 - AUG 20, 2023

Planned Owner Notification Date : AUG 20, 2023 - AUG 20, 2023

* NR - Not Reported