

# Part 573 Safety Recall Report

# 23V-499

**Manufacturer Name :** QUALITY VANS

**Submission Date :** JUL 19, 2023

**NHTSA Recall No. :** 23V-499

**Manufacturer Recall No. :** NR



## Manufacturer Information :

**Manufacturer Name :** QUALITY VANS

**Address :** 2113 W 7th Street

TEMPLE AZ 85281

**Company phone :** 480-464-7007

## Population :

**Number of potentially involved :** 10

**Estimated percentage with defect :** 100 %

## Vehicle Alterer Information :

**Vehicle 1 :** 2020-2023 Ford Transit

**Descriptive Information :** Cummins Power Generation notified our company that certain serial numbers had a concern with the fuel line system. The number of effected generators that were sold to QVSV by the vendor was 10. Out of the 10 that were sold to us, 2 of them were in our inventory and returned to Cummings Power. Make/Model - Onan QG 2800i EVAP, Part no. 2.8HGLAA-8303A.

**Production Dates :** JAN 05, 2020 - JAN 03, 2023

## Description of Defect :

**Description of the Defect :** This fuel hose between the inline fuel filter and the Injection Pump Module (IPM) may have inadequate clamp force, possibly resulting in a gasoline leak.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** A gasoline leak in the presence of an ignition source may increase the risk of fire.

**Description of the Cause :** The cause of the issue is an inadequate specification of the fuel hose.

**Identification of Any Warning that can Occur :** Bystanders may see or smell gasoline.

## Involved Components :

Component Name : Hose, Fuel

Component Description : Gasoline fuel hose between the IPM and fuel filter.

Component Part Number : A064P026

Component Name : Generator

Component Description : Onan QG 2800i

Component Part Number : 2.8HGLAA-8302A

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

NR

## Description of Remedy :

Description of Remedy Program : The remedy is to inspect and, if the unit has the defect, to replace the subject fuel hose and associated clamps. A recall-specific reimbursement plan will be provided on the Recall Portal for those units not covered by the manufacturer's limited warranty.

How Remedy Component Differs from Recalled Component : The remedy fuel hose has a unique part number A073T925.

Identify How/When Recall Condition was Corrected in Production : Production began with the remedy fuel hose on 02/21/2023.

## Recall Schedule :

Description of Recall Schedule : A list was given to Cummings/Onan about our customers that were involved. They explained to me that they would contact our customers to

get the recall taken care of. QVSV will follow up with notification letter to ensure our customers are getting the recall taken care of as well as direct phone calls to our customers.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : AUG 04, 2023 - NR

### **Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name :

Address :

Country :

Company Phone :

\* NR - Not Reported