

08/28/2023

23V-572 Chronology

1. All principal events that were the basis for the determination that the defect related to motor vehicle safety. Details about chronology of principal events are listed here below:

Warranty monitoring: from July 2023 there have been 2 warranty claims entered about rear shock failure due to a missing bushing.

2. A summary of all warranty claims, field, or service reports.

Warranty claim number	VIN	Model	Country	Warranty approval date	Item name	Description	km
6438079	██████████	V100 MANDELLO ROSSO MAGMA	Italy	24.07.2023	2B008297	Rear shock absorber	3850
6440593	██████████	V100 MANDELLO BIANCO POLARE	Italy	28.07.2023	2B008297	Rear shock absorber	3197

3. Other information (such as numbers of deaths and/or injuries), with their dates of receipt.

No deaths or injuries have been reported.