

Dealer Principal	General Manager	Sales Manager	Service Manager	Parts Manager	Marketing	Finance
Date: September 28, 2023 Bulletin #: A 09 2023 05 U		Source: Aftersales Name: Title: Phone #: Email:			Supersedes n	/a /a /a

Aftersales Bulletin

A 09 2023 05 - STOP023846

TECHNICAL CAMPAIGN (SAFETY RECALL 23V-645) – Complete as soon as possible, using all available means to recall the vehicle for correction.

PLEASE DO NOT SELL, LEASE OR DELIVER ANY VEHICLE COVERED BY THIS NOTIFICATION UNTIL THE DELIVERY STOP REPAIR HAS BEEN PERFORMED. THIS MEANS THAT DEALERS MAY NOT DELIVER NEW MOTOR VEHICLES TO A CONSUMER UNTIL IT IS FIXED OR USE/SELL REPLACEMENT EQUIPMENT/PARTS SUBJECT TO A DELIVERY STOP.

ALSO, YOU SHOULD NOT SELL, LEASE OR DELIVER ANY PROVENANCE (CPO) OR USED VEHICLES SUBJECT TO A DELIVERY STOP UNTIL THE REPAIR IS COMPLETED.

Affected Vehicles

This Delivery Stop affects Rolls-Royce Ghost (RR21/22) models produced from February 17th, 2020, to December 8th, 2022.

<u>Situation</u>

This bulletin will be replaced with bulletin AO9 2023 02 containing additional information regarding the Technical Campaign and remedy imminently.

Contact

If you have further questions, please contact your Regional Aftersales Manager (RAM).