Part 573 Safety Recall Report

Manufacturer Name :	Forest River, Inc.
Submission Date :	SEP 29, 2023
NHTSA Recall No. :	23V-659
Manufacturer Recall No. :	51-1682

Manufacturer Information :

Manufacturer Name : Forest River, Inc. Address : 55470 CR 1 P.O. Box 3030 Elkhart IN 46515-3030 Company phone : 1-800-348-7440

Vehicle Information :

Vehicle 1:	2021-2024 Forest Riv	ver Inc. Coachme	n Prism Class C Motorho	mes
Vehicle Type :	TRAILERS			
Body Style :	OTHER			
Power Train :	NR			
Descriptive Information :	Since inception of bot printed with an inacci 2021 PRISM PRC24 2022 PRISM PRC24 2023 PRISM PRC24 2024 PRISM PRC24 Grand Total 351	urate count of se IFS 101 IFS 87 IFS 140		g that was erroneously
Production Dates :	MAY 26, 2020 - SEP 1	3, 2023		
VIN Range 1:	Begin : NR	End :	NR	Not sequential
Vehicle 2:	2023-2024 Forest Riv	ver Inc. Coachme	n Concord Class C Motor	homes
	2023-2024 Forest Riv BUSES, MEDIUM & HI		n Concord Class C Motor	homes
	BUSES, MEDIUM & HI		n Concord Class C Motor	homes
Vehicle Type :	BUSES, MEDIUM & HI OTHER		n Concord Class C Motor	homes
Vehicle Type : Body Style :	BUSES, MEDIUM & HI OTHER NR	EAVY VEHICLES h models, both n	nodels received a FED Ta	
Vehicle Type : Body Style : Power Train : Descriptive Information :	BUSES, MEDIUM & HI OTHER NR Since inception of bot printed with an inacci 2023 CONCORD 2024 CONCORD	EAVY VEHICLES h models, both n urate count of se CNC321DSF CNC321DSF	nodels received a FED Ta at belts. 18	

Image: State of the state

Number of potentially involved : 370 Estimated percentage with defect : 100 %

Population :



Description of Defect :

Description of the Defect :	The Federal Placard may indicate a lower count of seat belts than what is installed into the vehicle.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	An incorrect Cargo Carrying Capacity may lead to an operator overloading the vehicle, which may lead to a crash. Potentially causing personal injury and/or property damage.
Description of the Cause :	An engineering clerical error.
Identification of Any Warning that can Occur :	

Involved Components :

(

Component Name 1:	Federal Placard
Component Description :	Federal Placard
Component Part Number :	N/A

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology :

On September 21, 2023, Forest River's Office of Corporate Compliance ("OCC") was made aware of that during a routine Corporate Pre-Delivery Inspection ("PDI"), the Federal Placard on the vehicles did not match seat belt positions.

On September 22, 2023, OCC opened a research item and met with the manufacturing plant.

On September 25, 2023, OCC began reviewing manufacturing records. OCC identified that the FED Tags to be inaccurate.

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

23V-659

On September 27, 2023, OCC was able to determine the scope of vehicles affected.

On September 29, 2023 Forest River's Office of Corporate Compliance voted to recall

Description of Remedy :

Description of Remedy Program :	Forest River will provide all parts and labor free of charge to Consumers and Dealers. A new accurate Federal Placard will be sent to Dealer and Consumers. Consumers may install the Federal Placard as per the instructions on the recall letter; or contact an Authorized Forest River Dealer and or Service Center to have the Federal Placard replaced. What is the Forest River Customer Service Phone Number? Coachmen Concord & Prism (574) 825-8602
	If you have already paid for a repair that is within the scope of this defect under recall, you still need to have this recall inspected and/or performed to ensure the correct parts and procedures were utilized. Additionally, you may be eligible for a refund of previously paid repairs. Refunds will only be provided for within the scope of this defect under recall. Please send the service invoice to the following address:
	Coachmen Prism & Concord Forest River, Inc. Attn: WARRANTY MANAGER PO Box 30 Middlebury, IN 46540
How Remedy Component Differs from Recalled Component :	Affected Component - Federal Placard The Federal Placard will now read the correct amount of belted positions.
	The week of September 25, 2023, the FED Tags were corrected to read the correct amount of belted positions.

Recall Schedule :

Description of Recall Schedule :	Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

23V-659

Planned Dealer Notification Date :NOV 08, 2023 - NOV 08, 2023Planned Owner Notification Date :NOV 08, 2023 - NOV 08, 2023

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573