RECALL 23V660 / 2023-537 REMEDY INSTRUCTIONS



Make(s): MANY, SEE BELOW Model(s): MANY, SEE BELOW Model Year(s): 2024 Concern: Manufacturing may have installed incorrect fuses into the vehicles power distribution center.

Turn off LP Gas at LPG Tank(s). Disconnect the vehicles' battery Positive and Negative, disconnect any House battery(s) Positive and Negative, if equipped with a generator ensure it is off and lastly, ensure the vehicle is disconnected from shore power. Block any tires/wheels to prevent the vehicle from rolling. Failure to do so may result in electrocution, fire or other personal injury, property damage and/or death.

CERTAIN: 2024 – BROOKSTONE: BKF344FL, BKF352RLD & BKF374RK CERTAIN: 2024 – CHAPARRAL: CHF334FL, CHF360IBL, CHF367BH & CHF375BAF CERTAIN: 2024 – CHAPARRAL LITE: CLF235RK, CLF274BH, CLF284RL, CLF30BHS & CLF30RLS CERTAIN: 2024 – SHASTA PHOENIX: SPF235RK, SPF25RE, SPF30BH, SPF30RLS, SPF334FL, SPF360BH, SPF370BAF & SPF373MBRB

REQUIRED RESOURCES:

FLASH LIGHT BLADE FUSE PULLER FUSES (MANY) – SOURCED LOCALLY

INSPECTION:

STEP 1: LOCATE THE POWER DISTIBUTION CENTER INSIDE THE VEHICLE;

STEP 2: PRESS THE LID AND IT WILL "POP" OPEN;

STEP 3: LOOK AT THE 12V DC FUSES;

- IF THE FUSES MATCH THE LISTING ON THE WHITE LABEL TO THE RIGHT OF THE FUSES, CLAIM THE INSPECTION ONLY <u>- DO</u> <u>NOT PROCEED</u>.
- IF THE FUSES <u>DO NOT MATCH</u> THE LISTING FUSES, MOVE ON TO THE REMEDY;

REMEDY:

STEP 1: REMOVE ANY FUSE THAT DOES NOT MATCH THE WHITE LABEL LISTING FOR THE FUSE SIZE;

STEP 2: INSTALL THE CORRECT FUSE(S) THAT IS LABELED FOR THAT PARTICULAR CIRCUIT NUMBER;

STEP 3: VERIFY EACH CIRCUIT WITH THE FUSE SIZE AGAIN TO MATCH THE WHITE LABEL, CIRCUIT NUMBER AND LOCATION IN THE DISTRIBUTION PANEL;

STEP 4: POWER THE VEHICLE ON AND VERIFY CORRECT OPERATIONS;

STEP 5: CLEAN AREA;

STEP 6: CLAIM REPAIR CODE.