MACK TRUCKS RECALL ALERT



Subject:	Safety Recall SC0450, Stability Control Programming
Recall Number:	SRA-M450
Date:	October 19, 2023
Applicable Markets:	⊠U.S. □Canada □ Export

Description

The electronic stability control may be inoperative due to the lack of yaw input as a result of a software programming error.

In the event of the need for stability control intervention, the vehicle may not have the ability to mitigate a loss of stability which may increase the risk of a crash.

There have been no field reports, warranty claims or customer complaints associated with this issue.

The remedy will be to program the ABS/ESP ECU with software which restores the functionality of the yaw sensor to the stability control program.

Model and Model Years Affected

 Certain 2024 Mack Anthem and Pinnacle model vehicles manufactured September 06, 2023 through September 11, 2023.

Vehicle Quantities

• 13 vehicles (All US)

Dealer Responsibilities

- The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act require dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.
- Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Notification Release Schedule

- Vehicle list will be posted on the Trucks Dealer Portal October 19, 2023.
- Owner notification letters will be released on or before December 03, 2023.
- Repair Instruction will be released once they are available.

Contact

If you have questions or concerns about this recall, contact the Regulatory Affairs Department at <u>vtna.regulatoryaffairs@volvo.com</u>.