

October 18, 2023

Mr. J.S. (Jurassic) Park VP/ Chief Safety Officer Kia America, Inc. 111 Peters Canyon Road Irvine, CA 92606-1790

Subject: Headliner Plate Detachment

Dear Mr. Park:

This letter serves to acknowledge Kia America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: KIA/BORREGO/2009-2014

Mfr's Report Date: October 13, 2023

NHTSA Campaign Number: 23V-692

Components: STRUCTURE:BODY:ROOF AND PILLARS

Potential Number of Units Affected: 22,768

Problem Description:

Kia America, Inc. (Kia) is recalling certain 2009-2014 Borrego vehicles. The headliner plates may not be secured properly, which can result in the plates detaching in the event of a side curtain air bag deployment.

Consequence:

A headliner plate that detaches during a crash may strike an occupant, increasing their risk of injury.

Remedy:

Dealers will secure the headliner plates, free of charge. Owner notification letters are expected to be mailed November 30, 2023. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC286.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107ES 23V-692

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarterly report was submitted.

Kia America, Inc.'s contact for this recall will be Emily C. Smith who may be reached by email at emily.c.smith@dot.gov. We look forward to working with you.

Sincerely,

Alae Anoly

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

