OMB Control No.: 2127-0004

Part 573 Safety Recall Report

23V-724

Manufacturer Name: Kia America, Inc.
Submission Date: OCT 30, 2023
NHTSA Recall No.: 23V-724
Manufacturer Recall No.: SC287



Manufacturer Information:

Manufacturer Name: Kia America, Inc.

Address: 111 Peters Canyon Road

Irvine CA 92606

Company phone: 800-333-4542

Population:

Number of potentially involved: 6,262 Estimated percentage with defect: 1 %

Vehicle Information:

Vehicle 1: 2015-2019 Kia Soul EV

Vehicle Type: LIGHT VEHICLES

Body Style: ALL

Power Train: HYBRID ELECTRIC

Descriptive Information: All 2015-2019 model year Soul EV vehicles manufactured from July 15, 2014 through

September 28, 2018.

The recall population was determined by a review of vehicle production. The vehicles subject to this recall were not produced in VIN order. Customers seeking information about their specific vehicle will be referred to Kia's Consumer Assistance Center or

their Kia dealer.

Production Dates: JUL 15, 2014 - SEP 28, 2018

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: When the vehicle is left unattended while powered ON and the parking brake is

not manually engaged, unintended vehicle movement may occur intermittently even though the gear shift lever is in the "P" (Park) position. This is caused by intermittent failure of the parking pawl to engage the parking gear, which Kia

suspects is due to damage to the parking mechanism within the GDU.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Unintended vehicle movement can increase the risk of a crash.

Description of the Cause: Intermittent failure of the parking pawl to engage the parking gear.

Identification of Any Warning None.

that can Occur:

Involved Components:

Component Name 1: GEAR DRIVE UNIT ASSY

Component Description: Gear Drive Unit (GDU) Assembly

Component Part Number: 44500-18400

Component Name 2: GEAR DRIVE UNIT ASSY

Component Description: Gear Drive Unit (GDU) Assembly

Component Part Number: 44500-18410

Supplier Identification:

Component Manufacturer

Name: Hyundai Transys

Address: 105, Sindang 1-ro, Seongyeon-myeon,

Seosan-si Chungcheongnam-do Foreign States 31930

Country: Korea, Republic of

Chronology:

See attached document titled "2015-2019MY Soul EV Gear Drive Unit Chronology".

Description of Remedy:

Description of Remedy Program: All owners of the subject vehicles will be notified by first class mail with

instructions to bring their vehicles to a Kia dealer. Dealers will be

instructed to update the Electronic Control Unit software for the Electronic Parking Brake (EPB) logic so that the EPB automatically activates when the gear shift lever is in the "P" (Park) position regardless of whether the vehicle is powered ON or OFF. [This recall replaces the prior 20V389 recall involving the 2015-2016MY Soul EV vehicles and is required regardless of whether those vehicles received the software update under that prior recall. To prevent any intermittent unintended vehicle

movement prior to completion of this recall, Kia recommends vehicle owners move the gear shifter in the 'P' (Parking) position and manually engage the EPB prior to exiting the vehicle.] Kia will reimburse owners for

repair expenses already incurred pursuant to Kia's General

Reimbursement Plan filed May 10, 2022.

How Remedy Component Differs Not applicable. from Recalled Component:

was Corrected in Production: sold in the U.S.

Identify How/When Recall Condition Not applicable. The 2019MY Soul EV is the last model year of that vehicle

Recall Schedule:

Description of Recall Schedule: The planned dealer notification is scheduled to begin and end on

December 19, 2023. The planned owner notification is scheduled to begin

and end on December 22, 2023.

Planned Dealer Notification Date: DEC 19, 2023 - DEC 19, 2023 Planned Owner Notification Date: DEC 22, 2023 - DEC 22, 2023

* NR - Not Reported