

**PARTS AVAILABILITY UPDATE:
SAFETY RECALL ACTION NOTICE 611 – ROCKET 3**

As stated in [TOL #25516](#), Triumph Motorcycles has initiated a voluntary safety recall affecting a specific VIN range of the below-referenced model.

Affected Models

SAFETY RECALL ACTION NOTICE 611
REAR BRAKE MASTER CYLINDER REPLACEMENT

MODEL CODE	MODEL	MODEL YEAR
YA1	ROCKET 3 GT TRIPLE BLACK	2022
YB1	ROCKET 3 R BLACK	2022
YJ1	ROCKET 3 GT	2020 - 2024
YK1	ROCKET 3 R	2020 - 2024
YL1	ROCKET 3 TFC	2020

VIN RANGE: 971477 to BR6550
(All Markets)

Key updates to this recall are as follows:

- Parts are in inventory at our warehouse and began shipping to dealers on Monday, November 6th
- Tool for the recall arrived to our warehouse on November 7th, and began shipping on November 8th

FEDERAL LAW PROHIBITS THE DELIVERY OF A RECALLED MOTORCYCLE UNDER A SALE OR LEASE UNTIL THE REMEDY HAS BEEN PERFORMED.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.

