# Part 573 Safety Recall Report

Manufacturer Name :Gulf Stream Coach, Inc.Submission Date :NOV 03, 2023NHTSA Recall No. :23V-742Manufacturer Recall No. :NR

## Manufacturer Information :

Manufacturer Name : Gulf Stream Coach, Inc. Address : P. O. Box 1005 503 S. Oakland Avenue Nappanee IN 46550

## **Population :**

Number of potentially involved :90Estimated percentage with defect :100 %

Company phone : 999-999-9999

# Vehicle Information :

|                           | 2024-2024 Gulf Stream Coach, Inc. Conquest, Independence, Trailmaster, Friendship,<br>Ameri-lite 177BH  |
|---------------------------|---|
| Vehicle Type :            |   |
| Body Style :              |   |
| Power Train :             | NR  |
| Descriptive Information : | Certain 2024 model year Conquest, Independence, Trailmaster, Friendship, Ameri-lite<br>Travel Trailers, model 177BH, manufactured by Gulf Stream Coach, Inc.<br>("Gulfstream") do not conform to 49 CFR Part 567 – Certification and Federal Motor<br>Vehicle Safety Standard 110 – "Tire Selection"<br>The 91 vehicles subject to this recall may contain incorrect Federal Certification<br>Labels that identify the tires as being ST205/75R14D with 3850 pounds GVWR at 75<br>PSI. The correct Federal Certification Label identifies the tires as being<br>ST205/75R14C with 3850 pounds GVWR at 60 PSI. |
| Production Dates :        | JUN 15, 2023 - OCT 30, 2023   |
| VIN Range 1:              | Begin : NR End : NR     Image: NR Image: NR   |

# **Description of Noncompliance :**

| -         | Certain 2024 model year Conquest, Independence, Trailmaster, Friendship,<br>Ameri-lite Travel Trailers, model 177BH, manufactured by Gulf Stream Coach,<br>Inc. ("Gulfstream") do not conform to 49 CFR Part 567 – Certification and<br>Federal Motor Vehicle Safety Standard 110 – "Tire Selection."<br>On the vehicles subject to this recall, the Federal Certification Label may<br>contain incorrect tire size and tire pressure information. Gross vehicle weight<br>rating (GVWR) remains the same. |
|-----------|--|
| FMVSS 1 : | 567 - Certification  |
| FMVSS 2 : | NR   |
|           |  |

The information contained in this report was submitted pursuant to 49 CFR \$573



23V-742

| art 573 Safety   | Recall Report   | 23V-742   | Page          |
|--|---|---|---------------|
| Description of the Safety Risk :                                 | If the original label applied is incorrect<br>inflation of the current tires. There is<br>could result in reduced traction and p<br>uneven tire wear potentially resulting<br>of crash. | a potential risk of over inflation w<br>performance of the tires as well as | hich<br>cause |
| Description of the Cause :                                       | Through a product change, the inform<br>in incorrect tire size and tire pressure<br>minimize the correct Endered Cartificat   | e information being made available  |               |
| Identification of Any Warning<br>that can Occur :                | printing the correct Federal Certificat<br>NR   | ion Ladeis originally installed.  |               |
| nvolved Components :   |   |   |               |
| Component Name 1 : N   |   |   |               |
| Component Description : N  |   |   |               |
| Component Part Number : N  | IR  |   |               |
|  |   |   |               |
|  |   |   |               |
|  |   |   |               |
| upplier Identification :   |   |   |               |
| Supplier Identification :<br>Component Manufacturer              |   |   |               |
| Supplier Identification :<br>Component Manufacturer<br>Name : NR |   |   |               |

#### **Chronology**:

Gulf Stream Coach became aware of the incorrect Federal Certification Label information through a quality yard audit of finished products on hand. Once identified, immediate containment of finished units on hand with incorrect Federal Certification Label information were segregated and labeled with DO NOT SHIP stickers until such time as replacement Federal Certification Labels with correct information were applied, audited and released for shipment.

The information contained in this report was submitted pursuant to 49 CFR §573

#### **Description of Remedy :**

| Description of Remedy Program :                                     | Gulf Stream Coach, Inc. will send replacement Federal Certification Labels, instructions and notification letters.  |
|---|---|
| <b>J</b>  | Incorrect Federal Certification Labels identify the tires as being<br>ST205/75R14D with 3850 pounds GVWR at 75 PSI. The correct Federal<br>Certification Label identify the tires as being ST205/75R14C with 3850<br>pounds GVWR at 60 PSI. |
| Identify How/When Recall Condition<br>was Corrected in Production : | Replacement Federal Certification Labels with correct information were created and applied.   |

## **Recall Schedule :**

| Description of Recall Schedule :   | Gulf Stream Coach will notify dealers and retail customers within 45 days. |
|------------------------------------|--|
| Planned Dealer Notification Date : | DEC 04, 2023 - DEC 04, 2023  |
| Planned Owner Notification Date :  | DEC 04, 2023 <sup>-</sup> DEC 04, 2023                                     |

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573