

Date: 1/11/2024

In-Vehicle/In-App Communication – Safety Recall Reminder

NHTSA ID: 23V-754

Subaru Recall ID: WRP23

Applicability: 2023 model year Subaru WRX, 2024 model year Crosstrek, 2024 model year Impreza, 2023-2024 model year Forester

Recall issue: Front drive shaft failure

Text:

Recall Description: Subaru of America, Inc. (Subaru) has initiated a safety recall for certain 2023 model year WRX vehicles, certain 2024 model year Crosstrek and Impreza vehicles, and certain 2023-2024 model year Forester vehicles.

Safety Risk Description: The vehicles included in this recall may be equipped with a front drive shaft assembly with an outer race that could crack, due to improper cooling during the manufacturing process. Over time, a cracked outer race could break, potentially resulting in loss of motive power. Additionally, if the outer race breaks, the vehicle may roll when parked if the parking brake is not applied. Both conditions increase the risk of a crash.

Remedy Description: For all potentially affected vehicles, Subaru dealers will inspect the left-hand and right-hand front drive shafts and where necessary, replace them with a new one at no cost to the customer.