The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Manufacturer Name :Airstream, Inc.Submission Date :NOV 17, 2023NHTSA Recall No. :23V-772Manufacturer Recall No. :NR

Manufacturer Information :

Manufacturer Name : Airstream, Inc.

Address : 419 West Pike Street PO Box 629 Jackson Center OH 45334-0629 Company phone : 937-596-6111

Vehicle Information :

Vehicle 1:	2019-2024 Airstream Interstate 19, Interstate 24, Interstate 24X, Rangeline, Atlas				
Vehicle Type :	LIGHT VEHICLES				
Body Style :	OTHER				
Power Train :	NR				
	The recall population was determined by a review of vehicle records of the labels that were printed The information on the labels did not match the specifications of the tires and rims.				
Production Dates :	MAY 21, 2018 - AUG 31, 2023				
VIN Range 1: H	Begin : 1B9	GUWA27KJ305800	End :	1B9GUWA24RJ311452	Not sequential
VIN Range 2: H	Begin: 1B9	HUWH29MJ306296	End :	1B9GUWH27RJ311449	Not sequential
VIN Range 3: H	Begin : 1B9	GUWH28PJ307410	End :	1B9GUWH2XRJ311431	Not sequential
VIN Range 4: H	Begin : 1BS	GUXE21RJ420175	End :	1B9GUXE2XRJ420417	Not sequential
VIN Range 5: H	Begin : 1B9	KUWH25PJ307262	End :	1B9KUWH23PJ311357	Not sequential

Description of Noncompliance :

-	The tire information printed on the Federal Certification label and Tire Placard are incorrect. Interstate 19 -The information printed was 47 psi, when it should have been for 52 psi. Interstate 24 GL/GT - The information printed was rim size of 16x6.5J, and should have been rim size of 16x5.5j. Interstate 24X - The information printed was rim size of 16x6J. Rangeline - Did not have the rim size field populated on the label. Atlas - The information printed was LT215/85R15 & LT215/85R15115 and should have been LT215/85R16.
FMVSS 1 :	110 - Tire selection and rims
FMVSS 2 :	NR
Description of the Safety Risk :	These non-compliance may cause a vehicle crash without prior warning.

RATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Population :

Number of potentially involved : 3,460 Estimated percentage with defect : 100 %



Part 573 Safety Recall Report

Description of the Cause : The information on the label differs from the tire and rim specifications.

Identification of Any Warning None. that can Occur :

Involved Components :

Component Name 1 :Federal Certification LabelComponent Description :Contains information relating to tire and rIm specificationsComponent Part Number :NR

Supplier Identification :

Component Manufacturer

- Name : NR Address : NR NR
- Country: NR

Chronology :

8/25/2023 - Airstream identifies the error with the Atlas tire size information.

8/28/23 - Airstream begins investigation.

9/1/2023 - Airstream touring coach Engineering identifies additional errors.

9/7/2023 - The safety committee meets and reviews all known data and determines a recall is warranted. Airstream is unaware of any warranty or injury claims due to this issue.

Description of Remedy :

Description of Remedy Program :	Corrected labels will be sent to affected customers and dealers for installation. This will be done at no cost to the owner.
	Interstate 19 -The label will be printed with the correct 52 PSI. Interstate 24 GL/GT - The label will be printed with the correct rim size of 16x5.5j. Interstate 24X - The label will be printed with the correct rim size of 16x6J. Rangeline - The label will be printed with the correct rim size of 16x6. Atlas - The label will be printed with the correct tire information LT215/85R16.

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Page 3

Identify How/When Recall Condition
was Corrected in Production :The issue was corrected on August 31, 2023. Any labels printed on
September 1, 2023 moving forward will be correct.

Recall Schedule :

Description of Recall Schedule :Airstream will send dealer and owner notification letters once approved
by NHTSA.Planned Dealer Notification Date :JAN 16, 2024 - JAN 16, 2024Planned Owner Notification Date :JAN 16, 2024 - JAN 16, 2024

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573