

U.S. Department of Transportation

National Highway Traffic Safety Administration

December 1, 2023

Mr. Jonathan Gannon BMW of North America, LLC 150 Chestnut Ridge Road Woodcliff Lake, NJ 07677 1200 New Jersey Avenue SE Washington, DC 20590

NEF-107DM 23V-797

Subject: Driver's Air Bag Inflator May Explode

Dear Mr. Gannon:

This letter serves to acknowledge BMW of North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BMW/X3/2014 BMW/X4/2014 BMW/X5/2014

Mfr's Report Date: November 24, 2023

NHTSA Campaign Number: 23V-797

Components:

AIR BAGS:FRONTAL

Potential Number of Units Affected: 486

Problem Description:

BMW of North America, LLC (BMW) is recalling certain 2014 X3 xDrive28i, X3 xDrive35i, X4 xDrive35i, X5 sDrive35i, and X5 xDrive35i vehicles. The driver's air bag inflator may explode during deployment, due to a manufacturing defect.

Consequence:

An inflator explosion may result in sharp metal fragments striking the driver or other occupants, resulting in serious injury or death.

Remedy:

Dealers will replace the driver's front air bag, free of charge. Owner notification letters are expected to be mailed January 16, 2024. Owners may contact BMW customer service at 1-800-525-7417.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:



You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in 49 U.S.C. § 30118(f), submission of eight consecutive quarterly reports followed by three annual reports is required. As described in 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter. The first of three consecutive annual status reports will be due on, or before, 1 year after the eighth quarterly report was submitted.

BMW of North America, LLC's contact for this recall will be DeMara Magruder who may be reached by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

