OMB Control No.: 2127-0004

Part 573 Safety Recall Report

23V-856

Manufacturer Name: Bombardier Recreational Products, Inc.

Submission Date: DEC 17, 2023 **NHTSA Recall No.:** 23V-856

Manufacturer Recall No.: Bulletin 2023-9



Manufacturer Information:

Manufacturer Name: Bombardier Recreational Products,

Inc.

Address: 726 Saint-Joseph Street

Valcourt, Quebec 00 JOE 2LO

Company phone: 450-532-2211

Population:

Number of potentially involved: 1,149

Estimated percentage with defect : 10 %

Vehicle Information:

Vehicle 1: 2023-2023 Can-Am F3 and F3-S

Vehicle Type: MOTORCYCLES

Body Style : OTHER Power Train : GAS

Descriptive Information: This recall will replace the previous safety recall (23V053) for MY2023 Can-Am

Spyder F3 and F3-S vehicles only.

It includes:

Model Year 2023 vehicles involved in the previous recall that were only

inspected.

Model Year 2023 vehicles that were not previously included and are already

sold to dealers or consumers.

Production Dates: SEP 28, 2022 - MAY 19, 2023

VIN Range 1 : Begin : NR End : NR

☐ Not sequential

Description of Defect:

Description of the Defect: The rearview mirror's lens may dislodge from the housing.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: This can result in an increased risk of a crash due to the decreased visibility

for the driver.

Description of the Cause: See chronology section.

Identification of Any Warning None

that can Occur:

Involved Components:

Component Name 1: HOUSING_REAR VIEW MIRROR RH ASSY

Component Description: Description: Mirror Housing Assembly - Right side

Component Part Number: 705015050

Component Name 2: HOUSING_REAR VIEW MIRROR LH ASSY

Component Description: Mirror Housing Assembly - Left side

Component Part Number: 705015049

Supplier Identification:

Component Manufacturer

Name: Zadi

Address: Via C. Marx, 138

CARPI (MO) Foreign States 41012

Country: Italy

Chronology:

In May 2023, some Model Year 2023 Can-Am Spyder F3 and F3-S vehicles were included in a safety recall regarding possible mirrors' lens falling from its housing. In monitoring its network, BRP saw a high rate of mirrors' lens still falling in the Model Year 2023 vehicles which were inspected during the safety recall process or in vehicles outside the safety recall population.

Nor BRP or its supplier have confirmed the exact root cause of the trend seen in its network. One hypothesis is a possible additional weakness created by possible housing inspection made in quality insurance or in the recall procedure. BRP did not want to wait for further analysis to address this situation. With all the information collected and analyzed, BRP decided on December 11, 2023, that it had enough information to report and wants to proceed with a safety recall.

The repair part for this recall will be assembled with a housing molded with a raw material from a different source which shows better resistance properties. This is also the raw material currently used in production.

The number of reported cases in the United States will be provided shortly. No accident was reported worldwide.

Description of Remedy:

Description of Remedy Program : BRP is issuing a safety recall and BRP will instruct to replace both mirror

assemblies. BRP will file its reimbursement plan if customers had already

paid for this issue.

How Remedy Component Differs The repair part for this recall will be assembled with a housing molded

from Recalled Component: with a raw material from a different source which shows better resistance

properties. This is also the raw material currently used in production.

Identify How/When Recall Condition The repair part for this recall will be assembled with a housing molded was Corrected in Production: with a raw material from a different source which shows better resistance

properties. This is also the raw material currently used in production for

MY2024.

Recall Schedule:

Description of Recall Schedule: BRP is issuing a safety recall bulletin on December 21, 2023. Customers:

BRP will start the mailing for consumers during the month of January

2024.

Planned Dealer Notification Date : DEC 21, 2023 - DEC 21, 2023 Planned Owner Notification Date : JAN 22, 2024 - JAN 22, 2024

* NR - Not Reported