OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 23V-873

**Manufacturer Name:** REV Ambulance Group Orlando, Inc.

**Submission Date:** JAN 08, 2024 **NHTSA Recall No.:** 23V-873

**Manufacturer Recall No.:** NR



#### **Manufacturer Information:**

Manufacturer Name: REV Ambulance Group Orlando, Inc.

Address: 2737 N. Forsyth Road

Winter Park FL 32792

Company phone: 800-628-8178

# **Population:**

Number of potentially involved: 210 Estimated percentage with defect: 100 %

#### **Vehicle Information:**

Vehicle 1: 2020-2024 REV Ambulance Group Orlan Type I, Type III, & Type IX

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: REV's Type I, Type III, and Type IX vehicles are equipped with Weldon's Vmux 8x16

Input/Output Node and are subject to recall. Weldon provided quantities and serial

numbers.

Production Dates: JAN 01, 2020 - JUN 30, 2023

## **Description of Defect:**

Description of the Defect: In the affected products, short circuit protection may not function properly. In

the case of a short circuit in the wiring or the connected load, overheating of

the wiring or the load may occur.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Depending on how the product is installed in the vehicle, this could increase

the risk of a vehicle fire.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

#### **Involved Components:**

Component Name 1: V-MUX 8 x 16 Input / Output Node

Component Description: I

Component Part Number: 6030-2000-00

# **Supplier Identification:**

## **Component Manufacturer**

Name: Weldon Division of Akron Brass

Address: 3656 Paragon Drive

Columbus Ohio 43228

**Country: United States** 

# **Chronology:**

REV Ambulance Gorup Orlando, Inc. (REVO) warranty department received a Technical Service Bulletin (TSB), regarding Equipment recall 23E-084. REVO was notified on December 13th, 2023. REVO conducted an inventory inspection on December 14th and determined that 235 units were affected. All units in-house (25 units) have been updated to correct the issue, per Weldon's provided instructions.

#### **Description of Remedy:**

Description of Remedy Program: If the vehicle is equipped with a V-MUX 8 x 16 Input / Output Node the end

user must perform a firmware update. Weldon will be responsible for

reimbursing the facility for performing the repairs.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition On December 13th we received notification from Weldon that there was was Corrected in Production: an issue with the VMUX 8 x 16 Input/Output Node. On December 14th we

identified the affected population and updated the firmware for the

affected components.

#### **Recall Schedule:**

Description of Recall Schedule: REV Ambulance Group Orlando will begin to notify dealers and

customers in January or sooner.

Planned Dealer Notification Date: JAN 15, 2024 - MAR 01, 2024 Planned Owner Notification Date: JAN 22, 2024 - MAR 01, 2024

Part 573 Safety Recall Report	23V-873	Page 3
* NR - Not Reported		
The information contained in this report was submitted	d pursuant to 49 CFR §573	