

## **IMPORTANT SAFETY RECALL** **STOP RETAIL SALES and DELIVERY**

Suzuki Motor Corporation has determined that a safety defect exists in certain 2024 Hayabusa (GSX1300RRM4) & Hayabusa 25<sup>th</sup> Anniversary Edition (GSX1300RRZM4) models:

Model	SPEC	V.I.N. Range
GSX1300RRM4	E03	JS1EJ11B#R7100201 - JS1EJ11B#R7101144
& GSX1300RRZM4	E33	JS1EJ11D#R7100027 - JS1EJ11D#R7100246

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Suzuki Motor Corporation (SMC) is initiating a safety recall campaign to tighten the brake pipe flare nuts on the motorcycle's ABS unit to the proper torque. Do not sell or deliver any new or used, affected Hayabusa motorcycle until the ABS Hydraulic Unit Flare Nut Tightening Recall service has been completed.

### **Service Bulletin & Safety Recall Repair:**

Information about performing the ABS Hydraulic Unit Flare Nut Tightening Recall service will be provided in a Service Bulletin coming on or after the week of January 29, 2024.

### **Parts Availability & Ordering:**

Parts are not required to perform the recall service. Suzuki Motor USA, LLC (SMO) may provide additional information regarding potentially related parts availability and ordering in the Service Bulletin mentioned above.

### **Customer Notification Letters:**


SMO expects to notify retail customers of this safety recall on or after the week of January 29, 2024.

### **How to Verify if a Hayabusa requires the Recall Service:**

This recall only affects certain 2024 (M4) Hayabusa models. Use the Vehicle History function of Suzuki CONNECT to determine if a particular Hayabusa requires the ABS Hydraulic Unit Flare Nut Tightening Recall service. If so, perform the recall service, and submit a warranty request as described in the bulletin.

If you need any additional information, please contact the Suzuki TECH-LINE (at 714-996-7480) or your Technical Service and Parts Manager (TSPM). We apologize for this inconvenience and will do everything possible to resolve this situation as quickly as possible.

Thank you for your continued support and understanding.

A handwritten signature in black ink, appearing to read "Chris Coons". The signature is fluid and cursive, with the first name "Chris" and the last name "Coons" clearly distinguishable.

Chris Coons  
Senior Manager, Motorcycle Sales Planning and Administration