

# Part 573 Safety Recall Report

## 24V-046

**Manufacturer Name :** Winnebago Towable**Submission Date :** JAN 26, 2024**NHTSA Recall No. :** 24V-046**Manufacturer Recall No. :** CAM0000034**Manufacturer Information :**

Manufacturer Name : Winnebago Towable

Address : 201 14th Street  
Middlebury IN 46540

Company phone : 825-5250

**Population :**

Number of potentially involved : 325

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2024-2024 Winnebago Access

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Recall was determined by Access production start date and notification of concern to production.

Production Dates : OCT 12, 2023 - JAN 11, 2024

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : On 2024 Access models the breakaway switch was incorrectly wired. An incorrectly wired breakaway switch prevents the breakaway switch from activating in the event the tow vehicle detaches from the trailer.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : An incorrectly wired breakaway switch will not engage the trailer brakes in the situation where the trailer becomes detached from the tow vehicle, which increases the risk of a crash in that condition.

Description of the Cause : The breakaway switch power wire is connected to ground rather than constant power.

Identification of Any Warning that can Occur : NR

**Involved Components :**

Component Name 1 : Breakaway Switch

Component Description : Breakaway Switch

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Winnebago Ind Inc.

Address : 201 14th Street  
Middlebury Indiana 46540

Country : United States

Chronology :

In January 2024, Winnebago Product Safety found a defect in wiring on Access models. The defect was found through dealership warranty submissions. Production was immediately notified, and the wiring was inspected. Upon inspection, it was determined the breakaway switch wiring was incorrect and the testing equipment experienced a fault setting.

On January 26, 2024 the Product Safety Committee decided the issue presented an unreasonable risk to motor vehicle safety.

Winnebago is aware of 30 dealership submissions with no incidents involving a customer. The first submission occurred November 14, 2023.

There are no injuries related to this issue.

Description of Remedy :

Description of Remedy Program : Reimbursement requests will follow the general reimbursement plan on file with NHTSA.

How Remedy Component Differs from Recalled Component : Winnebago Towables will provide instructions on how to correctly wire the breakaway switch.

Identify How/When Recall Condition was Corrected in Production : The condition was corrected in production immediately and the testing equipment was fixed. The correction was made on January 11, 2024.

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : JAN 31, 2024 - JAN 31, 2024

Planned Owner Notification Date : FEB 09, 2024 - FEB 09, 2024

\* NR - Not Reported