

# **VOLKSWAGEN DEALER COMMUNICATION**

## Advance Notice - Safety Recall 20UF / Suction Jet Pump

This notice is for: All Dealer Personnel

Date: February 16, 2024

Issue: The suction let pu

The suction jet pump inside the fuel tank is designed to purge fuel from the Evaporative Emissions (EVAP) system. If a specific seal inside an affected suction jet pump fails, the fuel may flow directly into the EVAP system. If this happens, fuel could accumulate in the EVAP system and may leak through the charcoal canister filter element. Leaking fuel, in the presence of an ignition source, may result in a fire.

Precautions: If the recall condition exists

If the recall condition exists in the vehicle, customers could experience refueling issues (early stopping fuel nozzles, spillback) when fuel has accumulated in the EVAP system. A fuel odor may also be noticed by the driver/vehicle occupants. Customers experiencing these issues are advised to contact an authorized dealer to have the vehicle diagnosed.

Repair:

- REPAIR NOT YET AVAILABLE
- Dealers and owners will be notified in writing once the remedy is available.
- Check daily campaign open inventory report or OMD for affected vehicles in inventory.

#### **Affected Vehicles**

| Country | Beginning<br>Model Year | Ending<br>Model Year | Vehicle         | Vehicle<br>Count |
|---------|-------------------------|----------------------|-----------------|------------------|
| USA     | 2015                    | 2020                 | GOLF            | 58,544           |
| USA     | 2015                    | 2020                 | GOLF GTI        | 114,485          |
| USA     | 2015                    | 2019                 | GOLF SPORTWAGEN | 26,037           |
| USA     | 2019                    | 2020                 | JETTA GLI       | 10,925           |
| CAN     | 2015                    | 2019                 | GOLF            | 57,293           |
| CAN     | 2015                    | 2020                 | GOLF GTI        | 15,783           |
| CAN     | 2015                    | 2019                 | GOLF SPORTWAGEN | 8,689            |
| CAN     | 2019                    | 2020                 | JETTA GLI       | 1,558            |

<sup>\*</sup>Counts reflect overall population; some vehicles may have already been repaired. Check Campaigns/Actions screen in Elsa <u>on the day of repair</u> to verify that a VIN qualifies for repair under this action. Elsa is the <u>only</u> valid campaign inquiry & verification source.

### Notes:

#### **IMPORTANT REMINDER: VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS**

<u>New Vehicles in Dealer Inventory:</u> It is a violation of federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

<u>Pre-Owned Vehicles in Dealer Inventory:</u> Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.

### -END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Volkswagen Public Relations.