Double wishbones Your Lamborghini Gallardo with chassis number: S. Agata Bolognese, 23.02.2006

Dear Sir or Madame,

In the course of continuous product monitoring, Automobili Lamborghini S.p.A. has found that the bolted connections on the double wishbones of some Gallardo models (model year 2006) may come loose over time or under extreme loading. This condition, when present, could lead to a reduction in handling stability.

For safety reasons it is therefore necessary to check and, if necessary, repair these vehicles. Your vehicle is one of the models affected.

We therefore kindly ask you to make your vehicle available to us for a maximum of 1-2 days so that we can carry out the necessary checks and repairs. This work will, of course, be carried out at no charge to you.

Please contact an authorised Lamborghini dealer or Service point without delay to make an appointment. Please bring this letter and your Service Schedule with you when you visit the workshop, so that we can make all necessary entries.

If you have any queries regarding this measure please contact your Lamborghini dealer or Service point.

Automobili Lamborghini S.p.A. provides additional the following hotline, available at Monday to Friday 9:00 to 18:00 (GMT):

Italian / French / Spanish: +39 349 459 8281

German / English: +39 349 459 8220 The information and procedures published below are strictly confidential and intended Mail to service/department@lamborghini.com/uals. All copyrights are the property of

Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A. We are sure you will appreciate the need for this precautionary measure, and regret any inconvenience caused by the extra workshop visit. If you have sold your vehicle or have taken it out of service, please complete the enclosed reply sheet and return it to us by fax as soon as possible.

Your co-operation will be appreciated.

Yours sincerely,

Automobili Lamborghini S.p.A.

S. Cieri (Proxy holder) M. Ceccarani (Head of Research & Development)

The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A. Automobili Lamborghini S.p.A. Customer Service and Spare Parts Fax: + 39 051 6817 709

Vehicle chassis No.:	
Vehicle cannot be checked because it has been	
□ scrapped	
□ stolen	
\Box sold to a domestic buyer	
\Box sold to an overseas buyer	
to new address:	
Name: First name:	
Street: House No.:	
Post code: Town:	
Country:	

Date / signature: