



DIREZIONE COMMERCIALE

After Sales – Spare Parts

---

Phone +39.051.6817764

Fax + 39.051.6817709

To : All Lamborghini Dealers

14 March 2002

Recall Campaign n. L147.R-01.02

Please follow very carefully all the instruction below.

Vehicle : Murciélago

Chassis numbers: see attached file

Technical information: check of the correct assembly and linkage steering box / joint steering shaft as explained on the attached procedure.

Solution: in the case of an improper assembly, please proceed to modify it as indicated in the picture.

Information to the customers: all the owners of all vehicles involved in the control have been informed by letter directly by Automobili Lamborghini.

Attached is a fac-simile of the letter sent to the customers.

Please inform your second hand department in order to have also the second hand cars checked and eventually modified before being sold.

Invoicing details: fill Warranty claim with the following details:

Description	Recall Campaign n. L147.R-01.02
-------------	---------------------------------



## DIREZIONE COMMERCIALE

After Sales – Spare Parts

---

Phone +39.051.6817764

Fax + 39.051.6817709

Cost Code 60

Problem Code 220

Component Code 04309

Operation code 04309110

Labour 0.50 for the quality control

Labour 1 for the control and the corrective action (when needed, please specify on warranty claim).

Warranty Manual: attached to the warranty manual a copy of the verification form with stamp and signature for validation.

### Important

Feedback: please fill the attached form and send it by fax to Lamborghini after Sales department +39.051.6817.709 once the operation had been carried over specifying the VIN of the vehicle and the result of the control.

Bernd Hoffmann  
Sales & Marketing Director

Giorgio Gamberini  
After Sales Manager