## **Service Update** 46650 Transmission Fluid Level Low



Reference Number:	N16-2046650	Release Date:	June 2016
GWM Number:	2046650	Revision:	00

Attention: This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

		Model Year		Model Year			
Make	Model	From	То	RPO	Description		
Chevrolet	Trax	2016	2016	LUV	1.4L Engine		
				F46	All-Wheel Drive		
				MNK	6-Speed Automatic		
					Transmission		

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

ſ	Condition	n On certain 2016 model year Chevrolet Trax vehicles equipped with a 1.4L engine (RPO LUV), All-Wheel			
		Drive (RPO F46) and a 6-speed automatic transmission (RPO MNK), the transmission fluid may be under			
		filled by 350ml. (11.8 fl oz.).			
- [	0	Observations in the second second fill to the mean endowed			

**Correction** Check the transmission fluid and fill to the proper level.

#### Parts

Quantity	Part Name	Part No.
1	Dexron VI Automatic Transmission Fluid 1Qt. (946 MI)	88865601
		19264717
		(Canada)

#### Warranty Information

Labor		Labor	Trans.	Net
Operation	Description	Time	Туре	Item
9102369	Fill Transmission to Correct Level	0.6	ZFAT	N/A

# Service Update 46650 Transmission Fluid Level Low



#### **Service Procedure**

- 1. Open the hood and install fender covers.
- 2. Remove the fluid fill cap.
- 3. Fill the transmission to the proper level with the correct fluid. Refer to *Transmission Fluid Level and Condition Check* in SI.
- 4. Install the fluid fill cap.
- 5. Remove fender covers and close hood.

#### **Dealer Responsibility**

Whenever a vehicle subject to this service update enters your vehicle inventory, or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

GM bulletins are intended for use by professional technicians, NOT a "<u>do-it-yourselfer</u>". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



We Support Voluntary Technician Certification

### GLOBAL SAFETY FIELD INVESTIGATIONS DCS4097 URGENT - DISTRIBUTE IMMEDIATELY

Date: June 30, 2016

- Subject: 46650 Service Update Transmission Fluid Level Low
- Models: 2016 Chevrolet Trax Equipped with 1.4L Engine (LUV), All-Wheel Drive (F46) and 6-Speed Automatic Transmission (MNK)
- To: All Chevrolet Dealers

General Motors is releasing Service Update 46650 today. The total number of U.S. vehicles involved is approximately 1,339. Please see the attached bulletin for details.

## Global Warranty Management (GWM)

The Investigate Vehicle History (IVH) screen in the GWM system will be updated July 1, 2016. A list of involved vehicles in dealer new inventory is attached to this message. Please hold all warranty transactions until the VIN appears in IVH.

END OF MESSAGE GLOBAL SAFETY FIELD INVESTIGATIONS