Service Department

Notice of Defect – 2006 to 2008 Model Year Lamborghini Gallardo Coupè and Spyder Installation of clutch pedal switch – Campaign n° 08 - 121 S. Agata Bolognese, 08.05.2008

Reference: VIN

Dear Sir or Madam:

This notice is sent to you in accordance with the requirements of Transport Canada Motor Vehicle Safety Act.

Automobili Lamborghini S.p.A. has decided that a defect which relates to motor vehicle safety exists in certain Model Year 2006 to 2008 Lamborghini Gallardo.

In the course of continuous product monitoring, Automobili Lamborghini S.p.A. has found that the clutch pedal switch was not installed on your vehicle. The engine could therefore be started without the clutch pedal being depressed. If the transmission were in gear when the engine is started without the clutch pedal depressed, the vehicle can experience movement in the forward or reverse direction unintended by the driver and an accident could possibly occur.

For safety reasons it is therefore necessary to update your vehicle and install a clutch pedal switch. Your vehicle is one of the models affected.

We therefore kindly request you to make your vehicle available for a maximum of 1 to 2 days so we can carry out the necessary repairs. This work will, of course, be carried out at no charge to you.

Transport Canada regulations require that any vehicle lessor receiving this Notice of Defect forward a copy to the lessee within 10 days.



Please contact an Authorized Lamborghini Dealer without delay to make an appointment. Please bring this letter and your Service schedule with you when you visit the workshop, so we can make all necessary entries.

If you have any queries regarding this action please contact:

Unlimited Motors, Inc.

Tel: 416-216-1160 Fax: 416-703-9290

Also your Authorized Lamborghini Dealer is available.

If your Authorized Lamborghini Dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Defect Investigator, Transport Canada at 800-333-0510 613-993-9851 if you are calling from the Ottawa region.

We are sure you will appreciate the need for this measure, and we regret any inconvenience caused by the extra workshop visit. If you have sold your vehicle or have taken it out of service, please complete the enclosed reply sheet and return it to us by fax as soon as possible.

Your co-operation is appreciated.

Yours sincerely,

Automobili Lamborghini, S.p.A.

S. Cieri (Proxy holder)

eggian

M. Reggiani (Research & Development Director)

127

È

Automobili Lamborghini S.p.A. Customer Service and Spare Parts Fax: + 39 051 6817 709

Vehicle chassis No.:
Vehicle cannot be checked because it has been
□ scrapped
□ stolen
\Box sold to a domestic buyer
\Box sold to an overseas buyer
to new address:
Name: First name:
Street: House No.:
Post code: Town:
Country:

Date / signature: