

TO: Mercedes-Benz Dealers, General Managers, Sales Managers, Service Managers, Parts Managers	FROM: Anthony Washington, Department Manager, Regulations and Certifications
Re: Service Campaign Notification Model 907 Sprinter Model Years 2019-2022 Update Vehicle Software	DATE: January, 2023

IMPORTANT SERVICE CAMPAIGN INFORMATION



Mercedes-Benz



Campaign No. :		Campaign Desc. :	Update Vehicle Software
2022120009		22V2790614	
This is to notify you of the upcoming Service Campaign to update software on approximately 115,115 MY 2019-2021 Mercedes-Benz Sprinter vans. All affected VINs will be flagged as "OPEN" in VMI.			
Background			
Issue	In addition to the recalls 2790611, 2790612 and 2790613 regarding the "Automatic transmission – Park pawl function", this service measure gets applied simultaneously along with the above mentioned recalls. This service measure will provide an alert to the driver in the event that the vehicle is not properly secured (according to the parking instructions in the operator’s manual; vehicle in “park” with the manual parking brake set).		
What We’re Doing	An authorized Mercedes-Benz dealer will update the software of various control units (incl. the ESP and transmission control units) in the affected vehicles. Please close out the service campaign using op code 02-2442 & 0.1hr. Because this measure is bundled with the previously launched “Park Pawl Function” recalls (2790611/2/3), there is no additional action required at the workshop.		
Parts	Software is Available		
Vehicles Affected			
Vehicle Model Year(s)	2019-2022		
Vehicle Model	907 Sprinter		
Vehicle Populations			
Total Vehicles	115,115		
Next Steps/Notes			
AOMS/SOMS	Please ensure your dealers have read and understand this notice		
While we regret any inconvenience this may cause, MBUSA are determined to maintain a high level of vehicle quality and customer satisfaction.			

