

PARTS BULLETIN

Subject: R59899: Brake Pedal Inspection	Group: 52	No: R59899
2019 XC 40	Market: US & Canada	
		Date: 8/22/18

Reference Bulletin QB R59899

Volvo Car USA LLC and Volvo Car Canada LTD (Volvo) on behalf of Volvo Car Group has decided to launch Recall R59899 on a **limited** number of model year 2019 XC40 vehicles.

Volvo has identified that the brake pedal may have been incorrectly riveted during the manufacturing process, and could result in the brake pedal moving out of position. If this condition would occur, it may lead to reduced braking performance, increasing the risk of a crash.

The corrective action is to inspect the brake pedal per the attached instructions, and replace it if necessary.

A total of 71 U.S. and 47 Canadian vehicles are eligible for this recall.

The following part number applies:

Part Number	Description	Qty
32212358	Brake Pedal	1

We have very limited stock of brake pedals at this time. To place an order for a vehicle with a verified brake pedal defect, contact Parts Support (Option 2) and provide them with the vehicle's VIN number. They will then release the part to you.