



02/24/2015

New Safety Recall Advanced Communication – R07022415

FCA US LLC announced a safety recall on certain 2015 model year (LA/LD) Dodge Challenger SRT and Dodge Charger SRT vehicles equipped with a 6.2L supercharged engine (sales code ESD).

Some of the above vehicles may experience a fuel leak at the engine fuel injector rail crossover hose. The engine fuel injector rail crossover hose may have been damaged during the manufacturing process. The damage cannot be reliably detected and may cause a fuel leak without warning. A leaking engine fuel injector rail crossover hose, in the presence of an ignition source, could cause an underhood engine fire.

Chrysler will conduct a voluntary safety recall on all involved vehicles to replace the engine fuel injector rail crossover hose.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations
FCA US LLC