



11/07/2016

New Safety Recall Advanced Communication – S85110716

FCA US LLC (“FCA US”) announced a safety recall on certain 2016 model year (WD) Dodge Durango and (WK) Jeep Grand Cherokee vehicles equipped with a 3.6L engine (sales code ERC).

Some of the above vehicles may have had the fuel rail crossover tube damaged during the engine manufacturing process. A damaged fuel rail crossover tube could leak fuel and cause an underhood engine fire without warning.

FCA US will conduct a voluntary safety recall to inspect the fuel rail crossover tube on all involved vehicles. Engines found with a damaged fuel rail crossover tube will have the fuel rail assembly and lower intake manifold replaced.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations
FCA US LLC