



11/18/2016

New Safety Recall Advanced Communication – S90111816

FCA US LLC (“FCA US”) announced a safety recall on certain 2017 model year (JK) Jeep Wrangler vehicles.

Some of the above vehicles may have been built with a fuel tank control valve that was improperly manufactured. An inoperative fuel tank control valve may result in a fuel leak during a vehicle rollover event, debris in the fuel tank, and/or the ability to overfill the fuel tank during refueling. A fuel leak during a vehicle rollover event, in the presence of an ignition source, could cause a fire without warning.

FCA US will conduct a voluntary safety recall to inspect the fuel tank control valve. Vehicles found with an improperly manufactured fuel tank control valve will have the fuel tank assembly and fuel pump module replaced.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations
FCA US LLC