## SAFETY RECALL



Rear Door Sealing Screen/Vapor Barrier Parts Update

> Reference: PC540 Date: March 1, 2017

CAMPAIGN

BULLETIN

## Attention: Dealer Principal, Sales, Service & Parts Managers

**IMPORTANT:** It is a violation of Federal law for retailers to sell or deliver vehicles in their inventory covered by this notification until the campaign action is performed.

Affected Models/Years:	Affected Population:		SERVICE COMM Activation date:	Stop Sale In Effect
MY2015-17 Altima (L33)	341,005	34,991	January 19, 2016	YES

## \*\*\*\*\* Parts Update\*\*\*\*

Nissan has temporarily placed harness protector patch (24271-0Z000) on parts restriction. Nissan anticipates unrestricting these parts later this month. In the interim, dealers may place an SVC order through DCS for any additional needs. Please refer to NPSB/16-526 for instructions on how to place an SVC order in DCS.

Orders will be filled as parts supply allows. There are currently 50,300 parts in dealer inventory.

## NISSAN NORTH AMERICA, INC.

Aftersales DIVISION