



To: U.S. and Canada Distributors
Dealer Principals
Service Managers
Warranty Managers
Parts Managers

Bulletin: SRA-V17-01
Date: April 21, 2017
Action Required? **YES**

From: Regulatory Affairs Department

Subject: RVXX1701, Pusher and tag axle ratings on certification label

Summary:

Description of Defect:

The gross axle weight rating for the pusher or tag axle may be incorrectly stated on the incomplete vehicle information label. This is a non-compliance with 49CFR567, Certification.

Models/ Model Years Affected:

Volvo: Certain 2015-2017 VHD model vehicles manufactured from August 29, 2014 through October 17, 2016 and shipped with spare tire(s) for the pusher or tag axle.

Vehicle Quantities:

Volvo: 65 Trucks in total all U.S.

Dealer's Responsibility:

The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.

Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Release Schedule:

- Vehicle list will be posted on the Trucks Dealer Portal April 21, 2017.
- Repair Instructions are tentatively scheduled for release by June 16, 2017.
- Owner Notices are scheduled to be mailed on or before June 16, 2017.

Questions:

Contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com if you have questions.