

ARA2 Stop Delivery / Recall Campaign – Checking rear left and right three-point belts and replacing them if necessary

ARA2 Stop Delivery / Recall Campaign - Checking rear left and right three-point belts and replacing them if necessary

| | |
|---------------------------------|---|
| ID Number | ARA2 |
| Models Affected | 911 (992) |
| Model Years | 2023 |
| VIN List | Attached |
| Number of Affected VINs | 897 |
| Issue Description | <p>On the rear three-point belts, there is a possibility that the automatic seat belt extension lock for mounting a child seat does not work properly.</p> <p>If this is the case, the belt extension lock can be switched off in an undefined manner, and the belt can then continue to be unrolled and pulled out. As a result, the child seat is not fixed in accordance with the specifications.</p> <p>To ensure the legally required operation of the belt extension lock, the three-point belts at the rear left and rear right must be checked and replaced if necessary.</p> |
| What should Porsche Centers do? | <p>Please arrange for the remedy to be carried out on affected vehicles as soon as possible.</p> <p>The remedy is now available as of 3/14/24</p> |
| What will Porsche do? | <p>Vehicles will have the remedy performed as soon as it is available. Customers will be contacted by PCNA via letter in the coming weeks to inform them of the Recall and remedy availability.</p> |
| Parts Ordering Instructions | <p>Supporting hardware can be ordered as needed.</p> |

ARA2 Stop Delivery / Recall Campaign – Checking rear left and right three-point belts and replacing them if necessary

All 3 point belts are only available via Car Down PDX order.

Please note that parts should only be ordered if the vehicle fails the check. We expect less than 1% of affected vehicles will require parts replacement.

TI Number

No. 32-24

Customer Letter

To be posted at a later date.

Customer Reactive Statement

To be posted at a later date.

Attachments

1. [VIN_List_Report_ARA2_2024-03-14_V2.xlsx](#)