



PORSCHE

**IMPORTANT SAFETY RECALL**

This notice applies to your vehicle: [REDACTED]  
NHTSA Recall Number: 15V-335

July 13, 2015

**Subject: Porsche Safety Recall AF05 – Wiring harness for left rear radiator fan  
2015 – 918 Spyder**

Dear Mr. Aghakhani,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Porsche has decided that a defect which relates to motor vehicle safety exists in certain 2015 Porsche 918 Spyder vehicles. Our records show that you are the owner of a vehicle affected by this action.

**What is the issue?**

Porsche has determined that there is a possibility that the wiring harness for the left rear radiator fan, located in the engine compartment, could make contact with a heat insulation plate made of carbon fiber. If the wiring harness makes contact, relative movements of the harness and the vehicle structure can damage wiring harness or the insulation on individual wires of the harness. This may lead to an electric short which could increase the risk of a fire even when the vehicle is unattended. As a precaution, owners are advised to park outside until the remedy has been made.

**What will we do?**

Porsche is conducting a safety recall on these vehicles. The affected vehicles will be brought to the workshop and the routing of the wiring harness will be inspected. The wiring harness will be secured to a coolant tube using an additional relocation clip. Any related wiring found to be damaged will be repaired or replaced as necessary. Of course, these repairs will be completed at no charge to you.

## IMPORTANT SAFETY RECALL

### **What should you do?**

Porsche will assist you in making contact with your authorized Porsche dealership to schedule a repair appointment as well as to arrange in advance for a Porsche loaner vehicle should you require alternate transportation from now until the completion of the repair. Once your vehicle is received at the authorized Porsche dealership, the actual repairs will take approximately 3-4 hours to complete. Isolated repair cases may increase the length of repair time to over 4 hours.

### **Lease vehicles and address change**

If you are the lessor and registered owner of the vehicle identified in this action, the law requires you to forward this letter immediately via first-class mail to the lessee within (10) days of receipt. If you have changed your address or sold the vehicle, please fill out the enclosed prepaid Owner Reply Card and mail it to us so we can update our records.

### **Can we assist you further?**

If your authorized Porsche dealer fails or is unable to complete this work free of charge within a reasonable length of time, please call or write:

Porsche Cars North America, Inc.  
Attn: Customer Commitment Department  
One Porsche Drive  
Atlanta, GA 30354  
1-800-PORSCHE

If you still cannot obtain satisfaction, you may file a complaint with:

National Highway Traffic Safety Administration  
1200 New Jersey Avenue, S.E.  
Washington, D.C. 20590

or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to <http://www.safercar.gov>.

We apologize for any inconvenience this matter may cause you. However, we are taking this action to help ensure your safety and continued satisfaction with your vehicle.

Very truly yours,  
PORSCHE CARS NORTH AMERICA, INC.



Tim Quinn  
Vice President, After Sales