



Mercedes-Benz

**IMPORTANT SAFETY RECALL 2016 100001**

**This notice applies to your vehicle,  
VIN: WDDUG6DB8FA123456  
Reroute Fuel System ECU Harness  
NHTSA Recall # 16V758**

Mercedes-Benz USA, LLC

Christian Treiber

Vice President  
Customer Services

October, 2016

2016100001  
WDDUG6DB8FA123456  
Daniel Selke  
1 Mercedes Drive  
Montvale, NJ 07645

Dear Mercedes-Benz Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Daimler AG (DAG), the manufacturer of Mercedes-Benz vehicles, has decided that a defect which relates to motor vehicle safety exists in certain Model Year 2017 E-Class vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

**What is the CONCERN?**

On certain E-Class vehicles, under certain loading conditions, the rear seat bench seat frame could damage the wiring harness to the fuel system control module. If the wiring harness is damaged, depending on the affected wire, it could affect the operation of the fuel pump, the fuel tank pressure sensor, or the fuel gauge. Should the fuel pump fail, the fuel supply to the engine would stop and the engine could subsequently stall. Depending on the traffic situation, this could increase the risk of a crash.

**What will your DEALER DO?**

An authorized Mercedes-Benz Dealer will reroute the wiring harness on the affected vehicles and repair it, if necessary. This service will be provided free of charge. We are dedicated to always delivering the best customer experience, and respect for your time is a top priority. While the minimum repair time is approximately **30 minutes**, your dealer can provide you with a better estimate of the overall time for this service visit. As a matter of normal service process, an authorized Mercedes-Benz dealer will also check for other repair measures which might be applicable to your vehicle and this may increase the required working time.

**What should YOU DO?**



To find the most convenient authorized Mercedes-Benz dealer from your smartphone, scan the QR code to the left.

For additional information and to schedule an appointment, please contact your preferred authorized Mercedes-Benz dealer at your earliest convenience. For additional authorized dealers, see [www.mbusa.com/recall](http://www.mbusa.com/recall). **Please mention you are scheduling an appointment to reroute the fuel system control unit wire harness under Recall Campaign # 2016 100001.** You may be asked for your 17-digit Vehicle Identification Number (VIN) which for your convenience is located above your name at the top of this letter.

**Information for Owners**

In the event that you are no longer the vehicle owner, or have had a change of address, please complete the reverse side and return the updated information in the enclosed envelope.

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

A VIN-based recall lookup tool on our MBUSA.com website now offers a search feature that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. See [www.mbusa.com/recall](http://www.mbusa.com/recall). Please also take the opportunity to update your email and phone contact information for any future recall notifications, which will supplement the owner notification letter.

Should you have any questions or encounter any difficulty regarding this Recall Campaign, please contact an authorized Mercedes-Benz dealer. If for any reason a dealer is unable to remedy your situation, we are always happy to hear from you. Please contact us at 1-(800) FOR-MERCEDES (1-800-367-6372).

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to <http://www.safercar.gov>.

We apologize for any inconvenience this situation may cause you.

Sincerely,



Mercedes-Benz – are registered trademarks of Daimler AG, Stuttgart, Germany

Mercedes-Benz USA, LLC  
303 Perimeter Center North  
Suite 202  
Atlanta, GA 30346  
Phone (770) 705-0600  
Fax (770) 705-0117  
[www.MBUSA.com](http://www.MBUSA.com)

**VIN: WDDUG6DB8FA123456**

☐ EXPORTED                      ☐ SOLD  
☐ LEASE, VEHICLE RETURNED    ☐ STOLEN  
☐ SCRAPPED                      ☐ OTHER

☐ MY NEW NAME OR ADDRESS IS:

Last Name, First NameStreetAptCityStateZIPEmail AddressPhone (numbers only)Mobile (numbers only)

**Signature**

### Reimbursement to Customers for Repairs Performed Prior to Recall

**Original or clear copy of all receipts, invoices and/or repair orders that show:**

- The name and address of the person who paid for the repair.
- The Vehicle Identification Number (VIN) of the vehicle that was repaired.
- What problem occurred, what repair was done, when it was done and who repaired it.
- The total cost of the repair expense that is being claimed.
- Proof of payment of repair (copy of front and back of cancelled check, or copy of credit card receipt).
- Reimbursement will be made by check from your dealer. If your claim is denied you will receive a letter from MBUSA within 60 days of receipt with the reason(s) for the denial.

**Please speak with your dealer concerning this matter.**

**THANK YOU FOR YOUR COOPERATION**