

IMPORTANT SAFETY RECALL 2016100003 This notice applies to your vehicle, VIN: WDDUG6DB8FA123456 Adjust Headlamp Aim NHTSA Recall # 16V759

Mercedes-Benz USA, LLC

Christian Treiber Vice President Customer Services

December, 2016

2016090001 WDDUG6DB8FA123456 Dan Selke 1 Mercedes Drive Montvale, NJ 07645

Dear Mercedes-Benz Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Daimler AG DAG), the manufacturer of Mercedes-Benz vehicles, has decided that certain Model Year 2016 GLE-Class vehicles fail to conform to Federal Motor Vehicle Safety Standard 108. Our records indicate that your vehicle is included in the affected population of vehicles.

What is the CONCERN?	On certain GLE-Class vehicles (166 platform), vehicles, the low-beam headlamps might not be adjusted according to specification and may deviate from the tolerance range required by Federal Motor Vehicle Safety Standard 108. A misaimed headlamp may not provide the optimal road illumination at night, and increase the risk of a crash.										
What will your DEALER DO?	An authorized Mercedes-Benz Dealer will check the basic setting of the headlamps on the affected vehicles and correct it if necessary. <u>This service will be provided free of charge</u> . We are dedicated to always delivering the best customer experience, and respect for your time is a top priority. While the minimum repair time is approximately 30 minutes , your dealer can provide you with a better estimate of the overall time for this service visit. As a matter of normal service process, an authorized Mercedes-Benz dealer will also check for other repair measures which might be applicable to your vehicle and this may increase the required working time.										
What should YOU DO?	For additional information and to schedule an appointment, please contact your preferred authorized Mercedes-										
To find the most convenient authorized Mercedes-Benz dealer from your smartphone, scan the QR code to the left.	Benz dealer at your earliest convenience. To locate authorized dealers see www.mbusa.com/recall. Please mention you are scheduling an appointment to adjust the headlamps under Recall Campaign # 2016100003. You may be asked for your 17-digit Vehicle Identification Number (VIN) which for your convenience is located above your name at the top of this letter.										
Information for Owners	In the event that you are no longer the vehicle owner, or have had a change of address, please complete the reverse side and return the updated information in the enclosed envelope.										

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

A VIN-based recall lookup tool on our MBUSA.com website now offers a search feature that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. See www.mbusa.com/recall. Please also take the opportunity to update your email and phone contact information for any future recall notifications, which will supplement the owner notification letter.

Should you have any questions or encounter any difficulty regarding this Recall Campaign, please contact an authorized Mercedes-Benz dealer. If for any reason a dealer is unable to remedy your situation, we are always happy to hear from you. Please contact us at 1-(800) FOR-MERCEDES (1-800-367-6372).

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY1-800-424-9153); or go to http://www.safercar.gov.

We apologize for any inconvenience this situation may cause you.

Sincerely,

le. Jusa

ightarrow Mercedes-Benz – are registered trademarks of Daimler AG, Stuttgart, Germany

Mercedes-Benz USA, LLC 303 Perimeter Center North Suite 202 Atlanta, GA 30346 Phone (770) 705-0600 Fax (770) 705-0117 www.MBUSA.com IMPORTANT

If for any reason YOU NO LONGER OWN THIS VEHICLE OR have a CHANGE OF ADDRESS, please COMPLETE THE SECTION BELOW, place in the ENCLOSED ENVELOPE, and DROP IN ANY MAIL BOX. If possible, provide the name and address of the present owner so that we may contact them.

 EXPORTED LEASE, VEHICLE RETURNED SCRAPPED 														SOL STO OTH	LEN														
	□ NEW OWNER INFORMATION □ MY NEW N															NAM	1E OF	R AD	DRE	SS I	S:								
La	st Nai	ne, F	irst l	Name	e								•		•				•		•				•				
Street Apt															1														
City State ZIP																													
En	nail Ac	dres	s						•					•										· · · · ·					
]														
Phone (numbers only)									1	Mobile (numbers only)																			
Date						_	Sign	aturo	e																				

**** PLEASE DO NOT DETACH. RETURN COMPLETE LETTER **** DO NOT USE THE ENCLOSED ENVELOPE FOR OTHER CORRESPONDENCE

Reimbursement to Customers for Repairs Performed Prior to Recall

If you have already <u>paid</u> to have this recall condition corrected you may be eligible to receive reimbursement. Requests for reimbursement may include parts, labor, fees and taxes. Reimbursement may be limited to the amount the repair would have cost if completed by an authorized Mercedes-Benz dealer. The following documentation must be presented to your dealer for reimbursement.

Original or clear copy of all receipts, invoices and/or repair orders that show:

- The name and address of the person who paid for the repair.
- The Vehicle Identification Number (VIN) of the vehicle that was repaired.
- What problem occurred, what repair was done, when it was done and who repaired it.
- The total cost of the repair expense that is being claimed.
- Proof of payment of repair (copy of front and back of cancelled check, or copy of credit card receipt).
- Reimbursement will be made by check from your dealer. If your claim is denied you will receive a letter from MBUSA within 60 days of receipt with the reason(s) for the denial.

Please speak with your dealer concerning this matter.

THANK YOU FOR YOUR COOPERATION