

15V-882
Model Year 2015 BMW i8
Dynamic Stability Control (DSC) Hydraulic Unit

Q1. Which models in the US are affected?

Affected are certain Model Year 2015 BMW i8 vehicles produced between May and June 2015.

Q2. How many vehicles in the US are affected?

Approximately 16 vehicles in the US are affected.

Q3. What is the specific issue involving this recall?

This recall involves the Dynamic Stability Control (DSC) hydraulic unit. Due to a manufacturing error, the DSC hydraulic unit may not have been produced to specification. As a result, it could lead to impairment of the DSC functions, including the braking function.

Q4. What can happen as a result of this issue?

If the DSC hydraulic unit became impaired, vehicle handling and control could be affected, increasing the risk of a crash.

Q5. Why are other models not affected?

Other models have been assembled with a DSC hydraulic unit produced to specification.

Q6. Can I become aware of this issue if it is occurring?

No.

However, for reference, if you need BMW Roadside Assistance, they can be contacted at 1-800-332-4269.

Q7. What corrective measures will be taken?

The DSC hydraulic unit will be inspected and, if necessary, replaced.

Q8. How did you become aware of this issue?

We became aware of this issue from our internal quality control procedures.

Q9. Are you aware of any accidents or injuries associated with the recall?

No.

15V-882
Model Year 2015 BMW i8
Dynamic Stability Control (DSC) Hydraulic Unit

Q10. Can I continue to drive my vehicle?

Yes.

When you receive a letter asking you to have this service performed, please do so as soon as possible.

If you are not the only driver of this vehicle, please advise all other drivers of this important information.

Q11. How will I be informed of the recall?

You will receive a letter via First Class mail in February advising you of this issue, and requesting that you bring your vehicle to your authorized BMW center for service and repair. When you receive this letter, please schedule an appointment with an authorized BMW center to perform the repair. You can find and contact your preferred BMW center at www.bmwusa.com/dealer.

Q12. Do I have to wait for my letter in order to have my recall performed?

Yes. We are in the process of implementing the recall campaign to ensure that the necessary parts and procedures are at our authorized BMW centers prior to requesting that you have the recall performed.

Q13. How will the recall be performed?

The DSC hydraulic unit will be inspected and, if necessary, replaced.

Q14. How long will the repair take?

This **free repair** may take up to one hour; however, additional time may be required depending upon your BMW center's schedule.

Q15. How many vehicles have experienced this condition?

The number of vehicles that may have this condition is unknown.