



AUTOMOBILE DIVISION
American Honda Motor Co., Inc.
1919 Torrance Blvd., - P.O. Box 2215
Torrance, CA 90509-9870

June 2014

NHTSA Recall 13V-382

IMPORTANT SAFETY RECALL NOTICE

Dear Honda Pilot Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

What is the reason for this notice?

Honda has decided that a defect which relates to motor vehicle safety exists in certain 2013 model year Pilot vehicles. There is a possibility that the engine pistons may not have received the proper heat treatment during manufacturing making them more susceptible to damage or premature wearing. A damaged or prematurely worn piston could cause the engine to stall, increasing the risk of a crash.

What should you do?

Call any authorized Honda dealer and make an appointment to have your vehicle's engine short block replaced **at no cost to you**. The complete replacement process may take approximately 11 hours; however, your vehicle will need to be at the dealer for a longer period of time. We recommend that you plan to leave your vehicle for at least 2 days to allow the dealer flexibility in scheduling.

Who to contact if you experience problems?

If you are not satisfied with the service you receive from your Honda dealer, you may write to:

American Honda Motor Co., Inc.
Honda Automobile Customer Service
Mail Stop 500-2N-7A
1919 Torrance Blvd.
Torrance, CA 90501-2746

If you believe that American Honda or the dealer has failed or is unable to remedy the defect in your vehicle, without charge, within a reasonable period of time (60 days from the date you first contact the dealer for a repair appointment), you may submit a complaint to:

Administrator
National Highway Traffic Safety Administration
1200 New Jersey Ave., SE
Washington, DC 20590

Or call the toll-free Safety Hotline at 888-327-4236 (TTY 800-424-9153), or go to <http://www.safercar.gov>.

What to do if you feel this notice is in error:

Registration records indicate that you are the current owner or lessee of a 2013 Honda Pilot involved in this campaign. If this is not the case, or the name/address information is not correct, please complete and sign the Information Change Card and return it in the enclosed postage-paid envelope. We will then update our records.

Lesser Information:

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.

If you have questions:

If you have any questions about this notice, or need assistance with locating a Honda dealer, please call Honda Automobile Customer Service at 800-999-1009, and select option 4. U.S. customers can also locate a dealer online at Honda.com. Customers in U.S. territories, please contact your local dealer/distributor.

We apologize for any inconvenience this campaign may cause you.

Sincerely,

American Honda Motor Co., Inc.
Honda Automobile Division

**IMPORTANT: SAFETY RECALL NOTICE
PLEASE OPEN IMMEDIATELY**

PLEASE DELIVER TO REGISTERED OWNER **JB5**

VEHICLE
IDENTIFICATION ►
NUMBER

PRINTED PERF ▼ PLEASE DETACH, SIGN BELOW AND PLACE IN RETURN ENVELOPE ▼

INFORMATION CHANGE CARD

PLEASE PROVIDE NAME AND ADDRESS CORRECTIONS ON THE REVERSE SIDE

[Empty box for name and address corrections]

◀ VEHICLE IDENTIFICATION NUMBER **JB5**

PLEASE SIGN AND RETURN THIS CARD
ONLY IF YOU HAVE MADE CHANGES

I no longer own the vehicle. It was:

- Sold (*print name and address of new owner on reverse, if known*)
- Exported
- Destroyed
- Stolen
- Lease expired, vehicle returned.
- Other: _____

Nota:

Si usted necesita esta información en español por favor comuníquese con Servicio al Cliente al 800-999-1009 y seleccione la opción 4.

Signature: **X** _____

Date: _____

SIGNATURE OF REGISTERED OWNER OR LESSEE REQUIRED

