

Questions and answers – ONLY FOR INTERNAL USE

Lamborghini Gallardo – manual transmission - model year “2006 – 2007 – 2008”

Lamborghini Murciélago – manual transmission - model year 2006 – 2007

“Clutch pedal switch – Canadian Market”

■ What is the problem on the affected vehicles?

The Canadian homologation rules foresee, for manual transmission, to push the clutch pedal in order to start the engine. It is missing the system to enable the engine start only when the clutch pedal is depressed.

■ What is the cause of this fault?

There has been an irregularity during the production process.

■ What effect does the fault have?

The vehicle is not compliant with the Canadian Transport regulation. The engine can be started even if the clutch pedal is not pushed.

■ How can the damage be identified?

It is possible to start the engine not pushing the clutch pedal.

■ Is there any risk for the car occupants?

Automobili Lamborghini S.p.A. is not aware of any accidents or other incidents resulting in injury to a person or damage to property.

The engine could therefore be started without the clutch pedal being depressed. If the transmission were in gear when the engine is started without the clutch pedal depressed, the vehicle can experience movement in the forward or reverse direction unintended by the driver and an accident could possibly occur.

■ Can I still use the vehicle ?

A workshop visit for carrying out the necessary checks/repairs should be arranged without delay with your Lamborghini dealer or Service point.

■ Which vehicles are affected ?

Lamborghini Gallardo – manual transmission, model year 2006 – 2007 – 2008
Lamborghini Murciélago – manual transmission , model year 2006 - 2007

■ Which chassis numbers are affected ?

32 Gallardo vehicles:

ZHWGC12N96LA02738	ZHWGC22N36LA03955	ZHWGC12N87LA05017
ZHWGC12N86LA02858	ZHWGC22N06LA04030	ZHWGC22N27LA05133
ZHWGC12NX6LA02859	ZHWGC22N56LA04072	ZHWGC12N17LA05179
ZHWGC12N16LA02930	ZHWGC22N96LA04138	ZHWGC22N37LA05206
ZHWGC12N86LA02987	ZHWGC22N97LA04240	ZHWGC22N97LA05355
ZHWGC12N16LA03141	ZHWGC12N27LA04235	ZHWGC12N47LA05371
ZHWGC12N96LA03324	ZHWGC22N47LA04274	ZHWGC12N17LA05389
ZHWGC12N46LA03392	ZHWGC22N57LA04414	ZHWGC22N67LA05393
ZHWGC22N66LA03688	ZHWGC12N37LA04759	ZHWGC22N87LA05590
ZHWGC12N36LA03691	ZHWGC22N07LA04787	ZHWGC22N68LA05766
ZHWGC22N96LA03751	ZHWGC22N07LA04983	

4 Murciélago vehicles:

ZHWBC26M26LA01948	ZHWBC37M77LA02227
ZHWBC37M67LA02123	ZHWBC37M87LA02270

The information and procedures published below are strictly confidential and intended exclusively for authorized operators and individuals. All copyrights are the property of Automobili Lamborghini S.p.A based on copyright law. The company reserves the right to make updates and modifications. The reprinting, reproduction, forwarding to unauthorized people and/or to third parties and partial or entire translation thereof are prohibited without written authorization from Automobili Lamborghini S.p.A.

Questions and answers – ONLY FOR INTERNAL USE

Lamborghini Gallardo – manual transmission - model year “2006 – 2007 – 2008”

Lamborghini Murciélago – manual transmission - model year 2006 – 2007

“Clutch pedal switch – Canadian Market”

■ Have any incidents already occurred on other customers' cars?

No, we are not aware of any incidents occurred.

■ What exactly needs to be repaired on the car?

A dedicated kit has been prepared to update the vehicles (pedal area, clutch pedal switch, GFA ecu).

■ How long will the repair work take?

Normally, the repair work will take 10 hours.

■ Will Automobili Lamborghini S.p.A. bear the costs of the repair work?

The costs of this campaign will be borne entirely by Automobili Lamborghini S.p.A.

■ Where can I have the repair work carried out ?

All Lamborghini dealers and Service points on the home market and abroad have been informed.

■ Is it necessary to make an appointment at the workshop?

Yes, the customer should contact a Lamborghini dealer or Service point.