

Campaign No. [REDACTED]

[REDACTED]

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: **Model 6 S U L Q W H U, Model Year 6 R I W Z D U H 8 S G D W H**

D ' Z • Sprinter Vehicles (platform 90), the Engine Control Unit (ECU) software, Transmission Control Unit (TCU) software and Dosing Control Unit (DCU) software does not correspond to current series production specifications.

Authorized Mercedes-Benz Sprinter dealer will update the Engine Control Unit (ECU) software, Transmission Control Unit (TCU) software and Dosing Control Unit (DCU) software.

Prior to performing this Recall Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Recall Campaign bulletin and follow the repair procedure exactly as described.

Please note that Recall Campaigns **do not expire** and may also be performed on a vehicle with a vehicle status indicator.

Approximately [REDACTED] vehicles are involved.

Order No. V-RC- [REDACTED] This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

