

SSM
46704

2016-2017 Explorer roof rack cap clips are now available as a separate part. It is no longer necessary to order a complete roof rack rail to obtain the cap retainer clips. To correct loose roof rack caps or broken or missing clips, order part # FB5Z-7851050-A. The package contains 7 clips.