

SSM 47008	Some 2018 Mustang vehicles equipped with the digital IPC may exhibit a "Service Tire Mobility Kit" message being displayed in the IPC. Press the OK button on the steering wheel to clear this message from the IPC. To prevent the message from returning on the next key cycle, press the settings button on the steering wheel, and in the menu, choose advanced settings> vehicle> tire mobility kit> 4 years. This should be performed even if the 4 years selection in this menu is already selected. Do not replace the tire mobility kit. Do not attempt any repairs at this time. Engineering is investigating, monitor OASIS for updates.
--------------	---