

SSM 47654	On 2019 Explorer vehicles equipped with a 2.3L EcoBoost engine, the engine cover has been deleted. The vehicle is not mis-built. The addition of any parts would not be considered a warrantable repair. Do not submit a claim for this condition.
-----------	--