

MFR Communi- cation ID	MFR Communi- cation Date	Make (Brand)	Model	Model Year	Text	
SSM 47852	3/12/2019	Ford	F-650/750	2016	Some 2017-2019 F-Super Duty and 2016-2019 F-650/F-750 vehicles built on or after 1-Oct-2017 equipped with a 6.7L engine may exhibit an intermittent oil pressure warning lamp. A revised oil pressure switch has been released; service part number GC3Z-9278-B. For removal and installation of the oil pressure switch refer to Workshop Manual, Section 303-01C. Applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual	
				2017		
				2018		
			F-SUPER	2019		
			DUTY	2017		
				2018		
				2019		