

SSM 47992 - 2017-2019 F-Super Duty - Tire Valve Stem Leak - Valve Stem Service Kit Available

Some 2017-2019 F-Super Duty vehicles equipped with tire pressure monitoring systems (TPMS) may exhibit a leak at the tire valve stem. The tire valve stem has been released as a separate service part kit. The new service part kit is available and it does not include the TPMS sensor. When replacing only the tire valve stem follow the procedure in Workshop Manual (WSM), Section 204-04A. For claiming, use causal part 1700 and applicable labor operations in Section 01 of the Service Labor Time Standards (SLTS) Manual.