

SSM 48049 - 2013-2018 Various Ford And Lincoln Vehicles - Adaptive Cruise Control/CollisionWarning Inoperative - DTC U3000:49 In CCM - Built On Or Before 19-Oct-2017

Some 2015-2017 F-150/Mustang, 2015-2018 Edge/MKC, 2016-2018 MKX, 2013-2018 Explorer/Taurus/Flex/MKT, and 2017-2018 Fusion/MKZ/Continental vehicles built on or before 19-Oct-2017 may exhibit an inoperative adaptive cruise control, collisionwarning, and/or collision avoidance system with a Pre-Collision Assist Not Available, Collision Warning Not Available, and/or Adaptive Cruise Fault message present in the instrument panel cluster (IPC) and diagnostic trouble code (DTC) U3000:49 present in the cruise control module (CCM). To resolve the condition, reprogram the CCM using the latest software level of the appropriate Ford diagnosticscan tool. For claiming, use causal part 9E731 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.

APPLICABLE VEHICLES

2015 - 2018 CAR: EDGE

2016 - 2018 CAR MKX

2017 - 2018 CAR: CONTINENTAL

2015 - 2017 TRUCK: F-150

2015 - 2017 CAR: MUSTANG

2015 - 2018 TRUCK: MKC

2013 - 2018 TRUCK: EXPLORER

2013 - 2018 TRUCK: FLEX

2013 - 2018 TRUCK: MKT

2013 - 2018 CAR: TAURUS

2017 - 2018 CAR: FUSION

2017 - 2018 CAR: MKZ