

SSM 48608 - 2019 Edge - Ambient Air Temperature Inaccurate

Some 2019 Edge vehicles may exhibit an incorrect or inaccurate ambient air temperature (AAT) reading. This may be due to the software in the front controls interface module (FCIM). To correct the condition, reprogram the FCIM with the latest software level of the appropriate Ford scan tool. For claiming use causal part 18842 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.