

SSM 49010 - 2017-2020 F-Super Duty – Brake Drag - Refer To Online Workshop Manual Diagnostics For Stoplamp Switch

Some 2017-2020 F-Super Duty vehicles may exhibit concerns related to brake drag. Utilize Workshop Manual (WSM) diagnostics in section 206-00 to verify the correct installation of the stoplamp switch. Improper adjustment of the stoplamp switch can cause the brake pedal assembly to lightly apply the brakes resulting in dragging condition.

APPLICABLE VEHICLES
2017 - 2020 TRUCK: FE P558N SUPER DUTY