

SSM 49132 - 2020 Mustang GT500 - Exhaust Tailpipe Actuator - Updated Diagnostics

Some 2020 Mustang GT500 vehicles may exhibit various concerns with the exhaust tailpipe actuators. Workshop Manual (WSM) diagnostics have recently been updated to assist in better diagnosis of these concerns. Refer to WSM, Section 303-14D.

APPLICABLE VEHICLES
2020 CAR: ZG S550N MUSTANG