

SSM 49210 - 2009-2020 Various Vehicles - Turbocharger Oil Supply Tube/Drain Tube/O-ring Or 6.7L Pedestal Gasket Oil Leaks

Some 2009-2020 Ford and Lincoln vehicles equipped with turbochargers may exhibit an oil leak from the turbocharger oil supply or return tubes, O-rings or 6.7L pedestal gasket. Although oil may collect on the turbocharger, it is very rare for a turbocharger to leak oil. To isolate the source of the leak, refer to Workshop Manual (WSM), Section 303-00 General Information > Diagnosis and Testing > Engine > Engine Oil Leaks - Fluorescent Oil Additive Method procedure. When an oil leak is present at a turbocharger oil supply or drain tube, remove the affected oil tube and inspect for damage, and replace the O-ring seals, pedestal gasket or oil tube as required. Refer to WSM, Section 303-04. For claiming, use the affected oil tube or pedestal gasket as the causal part and applicable labor operations in Sections 6 and 9 of the Service Labor Time Standards (SLTS) Manual.

APPLICABLE VEHICLES

2017 - 2020 CAR: PL D544N CONTINENTAL
2017 - 2020 CAR: PL D544N CONTINENTAL
2017 - 2019 TRUCK: M2 C520N ESCAPE
2013 - 2016 TRUCK: M2 C520N ESCAPE
2013 - 2016 TRUCK: M2 C520N ESCAPE
2017 - 2019 TRUCK: M2 C520N ESCAPE
2015 - 2017 TRUCK: B7 U222N EXPEDITION
2011 - 2015 TRUCK: UB U502N EXPLORER
2016 - 2019 TRUCK: UB U502N EXPLORER
2013 - 2019 TRUCK: UB U502N EXPLORER
2020 CAR: TW U625N EXPLORER
2013 - 2018 TRUCK: WJ U502E EXPLORER
2015 - 2020 TRUCK: FC P552N F-150
2018 - 2020 TRUCK: FC P552N F-150
2015 - 2020 TRUCK: FC P552N F-150
2019 - 2020 TRUCK: FC P552N F-150
2016 - 2019 TRUCK: BC H567N MEDIUM TRUCK
2016 - 2019 TRUCK: BC H567N MEDIUM TRUCK
2016 - 2019 TRUCK: BC H567N MEDIUM TRUCK
2014 - 2017 CAR: CT B299N FIESTA MCA
2014 - 2019 CAR: CT B299N FIESTA MCA
2010 - 2019 TRUCK: P3 D471N FLEX
2018 - 2020 CAR: GH C519A FOCUS
2018 - 2020 CAR: GH C519A FOCUS
2015 - 2018 CAR: EW C346E FOCUS MCA
2015 - 2018 CAR: DH C346N FOCUS
2013 - 2018 CAR: DH C346N FOCUS
2017 - 2020 CAR: GX S922N GT
2011 - 2016 TRUCK: FA P473N SUPER DUTY
2013 - 2015 CAR: C7 CD391N FUSION
2013 - 2020 CAR: C7 CD391N FUSION
2017 - 2019 CAR: C7 CD391N FUSION
2015 - 2019 TRUCK: ME C489N MKC
2015 - 2016 TRUCK: ME C489N MKC
2017 - 2019 TRUCK: ME C489N MKC
2015 - 2019 TRUCK: ME C489N MKC
2010 - 2016 CAR: LE D385N MKS
2013 - 2016 TRUCK: P4 D472N MKT
2010 - 2019 TRUCK: P4 D472N MKT
2015 - 2020 CAR: C9 CD533N MKZ
2013 - 2020 CAR: C9 CD533N MKZ
2017 - 2020 CAR: C9 CD533N MKZ
2015 - 2020 CAR: C9 CD533N MKZ
2013 - 2020 CAR: C9 CD533N MKZ
2017 - 2020 CAR: C9 CD533N MKZ
2015 - 2017 TRUCK: B5 U228N NAVIGATOR
2013 - 2019 CAR: PH D258N TAURUS
2010 - 2019 CAR: PH D258N TAURUS
2011 - 2015 TRUCK: UB U502N EXPLORER
2016 - 2019 TRUCK: UB U502N EXPLORER
2013 - 2019 TRUCK: UB U502N EXPLORER
2013 - 2019 CAR: PH D258N TAURUS
2010 - 2019 CAR: PH D258N TAURUS

2020 TRUCK: TH V363N TRANSIT
2014 - 2020 CAR: C7 CD391N FUSION
2014 - 2020 CAR: C7 CD391N FUSION
2013 - 2015 CAR: C7 CD391N FUSION
2013 - 2020 CAR: C7 CD391N FUSION
2017 - 2019 CAR: C7 CD391N FUSION
2014 - 2019 TRUCK: TH V363N TRANSIT
2020 CAR: TV U611N AVIATOR
2020 CAR: TV U611N AVIATOR
2020 CAR: TF CX483N CORSAIR
2020 CAR: TF CX483N CORSAIR
2016 - 2020 CAR: D9 U540N MKX
2016 - 2020 CAR: D9 U540N MKX
2018 - 2020 TRUCK: B9 U554N NAVIGATOR
2015 - 2020 CAR: DQ CD539N EDGE
2015 - 2020 CAR: DQ CD539N EDGE
2018 - 2020 TRUCK: B8 U553N EXPEDITION
2020 CAR: TW U625N EXPLORER
2020 CAR: TW U625N EXPLORER
2020 CAR: TW U625N EXPLORER
2015 - 2020 CAR: ZG S550N MUSTANG
2020 CAR: ZG S550N MUSTANG
2019 - 2020 TRUCK: FG P375N RANGER
2014 - 2020 TRUCK: TH V363N TRANSIT